


Interaction Plot 1

The GLM Procedure


Dependent Variable: wear



Interaction Plot 2

The GLM Procedure

Dependent Variable: wear



Tukey Test for Interaction

The GLM Procedure

Dependent Variable: wear

Contrast	DF	Contrast SS	Mean Square	F Value	Pr > F
Tukey eta	1	27.13275417	27.13275417	2.19	0.1522